OH Schit...



Date: 3/03/2022

Division/Project: Denver / X1426 SCL West

Title: Multiple Trade Awareness



What the *#\$!?

Apollo teams were working around multiple trades at a ground-up hospital that is in stages of steel erection. During steel erection, the iron trade lost control of angle iron being maneuvered with a chain fall and dropped the angle iron two stories to ground level. Apollo teams were feet away from the area when they witnessed the angle iron land on gang box.

Lady Luck highlights of what went right

- No one was struck by the angle iron.
- Apollo teams reported the near miss to safety and GC immediately.
- Apollo employees were aware of the multiple trade work and were clear of the designated lifting area.

Did we get that on film?



The Oops!

The angle iron did not have tag lines/tethers and control of the material was lost as it was being hoisted by iron trade and placed using a chain fall.

Would of, Could of, Should of

- Communication with other trades on site is key. Apollo employees were not in the area due to prior communications and barricading.
 - Tag lines/tethers can help control the material while using a "knock it into place" method can result in loss of control.
- Stay aware of the work other trades are completing. Stay out of the line of fire. Stay out of barricaded areas.