


Lessons Learned

Date: 3/7/2023 Region: JB Southern Division
 Project: Oregon Intel Tool Install Incident Title: Fall From Ladder

Summary	Picture
<p>Worker was installing labels on PCW line and monitoring the Pressure test. When worker was Standing on the 4/5th rung of the ladder, the ladder tipped over and the worker fell into a pushup position. Worker's legs hit side of ladder like a whip, causing Multi level laceration to right leg.</p>	
What Went Right?	What Went Wrong?
<ul style="list-style-type: none"> • Worker called and reported incident. • Worker was Able to return to work. 	<ul style="list-style-type: none"> • Ladder was not supposed to be used outside the Fab level. This ladder was a stocker use only ladder. (Narrow ladder) • Worker reached out enough to make ladder unstable. • Click or tap here to enter text.
Lessons Learned	
<ul style="list-style-type: none"> • Plan the work to make sure the right ladder is being used. • Use Apollo given equipment in your work area. • Make sure there is a plan to be rescued you if something should happen. 	