


Lessons Learned

Date: 4/6/2023	Region: Southern JB Division
Project: Tool Install Hillsboro	Incident Title: Unattended Vehicle Accident

Summary	Picture
<p>DC driver was tasked to deliver paycheck to the onsite GF tent. When driver arrived at the location, they parked in a no parking zone. The driver left the hazard lights on and the vehicle running. The driver exited the vehicle and ran the check into the field office. When he returned 2 minutes later, the truck was not there. After looking around, the driver noticed the vehicle had hit another vehicle parked at the Loading dock.</p>	
What Went Right?	What Went Wrong?
<ul style="list-style-type: none"> No one was hurt. Called the supervisor and reported the incident. Driver activated the QR code to see what steps were needed to complete incident. <p style="font-size: small; margin-top: 5px;">Click or tap here to enter text.</p>	<ul style="list-style-type: none"> The vehicle was left running. Unattended while running. Parked in a no parking zone. While vehicle was running, the emergency brake was not activated.

Lessons Learned
<ul style="list-style-type: none"> Double check that the gear shift is engaged in the proper position before leaving vehicle. Don't leave the vehicle running when unattended. Follow site parking procedure when leaving vehicle behind. Don't take chances, double check that all procedures are in place when exiting any vehicle. (Engine off, brake set, wheels chocked when needed per site policies.)